

Lower Columbia College
Longview, WA

Welding Tools List

Arc Welders

1. Goggles
2. Gloves (**light weight for Oxy/Fuel**)
3. Full Leather Jacket or Fire-Retardant Jacket
4. Boots
5. Vise Grips, Pliers, Channel Locks
6. Tip Cleaners
7. Chipping Hammer
8. Wire Brush
9. Welding Helmet w/flip or Electronic Helmet (**preferably a Flip lens**)
10. Safety Glasses (Side shields)
11. Ear Plugs
12. Coveralls or Leather Apron (optional)

Gas Welders Need Everything on the list above except for: welding helmet and chipping hammer.

-
1. **All** students must attend a safety orientation class prior to working in the lab.
 2. The above tool list is a must
 3. No synthetic or nylon clothing may be worn in the shop
 4. People in Welding 221 and 222 (wire feed) must have their own wire cutters
 5. **Romeo's are not acceptable safety shoes in the welding trade and are not allowed in the LCC welding lab.**