

## Report Summary

Report Name: XYZ Data Center  
Completed for: XYZ Company  
Inspection Date: July 12, 2021  
Location: Anywhere, USA  
Contact: Bill Smith, Superintendent  
Score: 76.5%

**Scope of Work:** Test job to demonstrate new "Large Photo" template

### Opportunities for Improvement:

#### Cranes

**Issue Identified:** Accessible areas within swing radius of crane are not barricaded to prevent workers from being struck or crushed (1926.1424) (See Photo)

**Recommendation:** All accessible areas within the swing radius of a crane shall be barricaded to prevent workers from being struck or crushed. Take appropriate action to address issues of non-compliance. [reference 1926.1424(a)] [View OSHA Standard](#)

**Notes:** Need to install radius guard on crane

**Severity:** Moderate 1

**Responsible Party:** The Final Company



## Fueling Operations

**Issue Identified:** Fuel tanks are not properly labeled/identified (NFPA 30) (**See Photo**)

**Recommendation:** Take steps to ensure fuel tanks are properly labeled and/or identified with fuel name stenciled on tank, flammable placards, etc. per requirements in NFPA 30 and/or applicable local/state codes.

**Notes:** Improper labeling on fuel tanks. Need to contact company that services the tanks.

**Responsible Party:** Glidden LLC



No labels and no berm.

## Ladders/Stairs

**Issue Identified:** Top of ladder/side rails are not secured as needed to prevent side shift (1926.1053) (**See Photo**)

**Recommendation:** Take appropriate steps to ensure ladder side rails are secured to a rigid support to prevent the top of ladder from shifting (i.e. slipping sideways and possibly falling over). [reference 1926.1053(b)(1)] [View OSHA Standard](#)

**Notes:** This ladder was not secured. It was being used by multiple contractors to access the roof on the west side of building.

**Severity:** Serious Deducts 5%

**Responsible Party:** Glidden LLC



## PPE

**Issue Identified:** Appropriate hand protection is not worn as required (1926.28) (**See Photo**)

**Recommendation:** Take steps to ensure employees use appropriate hand protection (i.e. leather, chemical resistant gloves, cut-resistant gloves, etc.) where hands are exposed to hazardous conditions. [reference 1926.28(a)]  
[View OSHA Standard](#)

**Notes:** Gloves are required when using adhesives to connect PVC pipes. No gloves were being used.

**Responsible Party:** The Final Company



Need to use gloves when handling adhesives

## Other/Misc.

**Issue Identified:** An unsafe condition was identified that could potentially cause serious physical harm to employees if not corrected. See notes and/or photos for additional detail (5a1) (**See Photo**)

**Recommendation:** Take steps to address the unsafe condition (or conditions) identified during the inspection that could potentially cause serious physical harm to employees if not corrected. [reference OSHA Section 5(a)(1)]  
[View OSHA Standard](#)

**Notes:** Stairs to storage trailer need to be repaired, add hand rail on right side.

**Responsible Party:** Glidden LLC



These stairs need to be repaired or replaced!

## Positive Findings:

### Cranes

- Positive Finding** Required operational aides (i.e. boom angle/radius indicator, boom/jib hoist limiting device, anti two-blocking device, etc.) are installed and maintained (1926.1416)
- Positive Finding** Crane(s) and attachments are operated per manufacturer procedures (1926.1417)
- Positive Finding** A visual inspection by a competent person is completed each shift the equipment is used (1926.1412)
- Positive Finding** The rated capacities (load charts), instructions and operator's manual are kept in cab(1926.1417)
- Positive Finding** Accessible areas within swing radius of crane are barricaded to prevent workers from being struck or crushed (1926.1424)

### Photo(s)



- Positive Finding** Only qualified riggers are allowed to perform rigging duties (1926.1425)
- Positive Finding** Crane operator meets all Federal, State and/or Local certification requirements (1926.1427)
- Positive Finding** Signal person(s) trained, qualified and authorized to perform duties (1926.1428)
- Positive Finding** Fire extinguisher of 5BC rating or higher is available at the operator station and/or cab (1926.1433)

### Electrical Safety

- Positive Finding** Ground pins are attached to electrical cords (i.e. extension cords and/or flexible cord sets) (1926.404)
- Positive Finding** GFCI is used for temporary power connections (1926.404)

### Photo(s)



- Positive Finding** Cord sets and/or Power Supply cords are used per Listing (i.e. not interconnected or "daisy chained") (1926.403)
- Positive Finding** Flexible cords are maintained in good condition (1926.416)

- Positive Finding** Breakers, switches and/or other disconnecting means are legibly marked to indicate purpose (1926.403)
- Positive Finding** Electrical panels/circuits are effectively enclosed (1926.405)

**PPE**

- Positive Finding** PPE maintained in a sanitary/reliable condition (1926.95)
  - Positive Finding** ANSI approved eye protection is used as required (1926.102)
  - Positive Finding** Face protection is used when sawing, cutting, grinding, welding, etc. (1926.102)
- Photo(s)**



- Positive Finding** Hard hats are worn as required (1926.100)
- Positive Finding** Appropriate safety footwear is worn as required (1926.28)
- Positive Finding** Hearing protection is provided/used as required (1926.52)

**Safety Training**

- Positive Finding** Toolbox talks are completed weekly per company policy (1926.21)
- Photo(s)**



## Recommendations:

Score Summary	#	Severity Summary	Qty
Issues Identified:	5	NA 1	3
Positive Findings:	22	Advisory 1	0
Total Findings:	27	Minor 1	0
Percent Positive:	81.5%	Moderate 1	1
Severity Adjustment:	5.0%	Serious Deducts 5%	1
Final Score:	76.5%	Critical Deducts 10%	0

---

Submitted by:  
John Doe  
Safety Consultant  
My Company, LLC  
(555) 234-5678  
johndoe1963@cox.net

*DISCLAIMER: Observations and recommendations are purely advisory and based on practices and conditions observed and information provided at the time of this survey. They are not intended to include every loss or accident potential. It's the client's responsibility to make further observations and take whatever action that may be necessary to prevent losses, enforce safety procedures and eliminate hazardous conditions so as to comply with any federal, state, or local law, rule or regulation concerning safety and health.*